

In order to provide accurate data for the IPSC work to be done during the outage it will be necessary to use separate time sheets for this work. Also it will be necessary to break the different tasks out on these separate time sheets.

SAFETY WELDER 3021

**Removing burner nozzles and diffusers, cleaning elbows and bolts should be charged to:

90025.1 23,200 X

DIFFUSER

**Removing and replacing coal nozzles should be charge to:

90025.2 10,200

DIFFUSER?

**Burning, air arcing, etc. to remove the nozzle should be charged to:

90025.3 4,500

③ **Installation of stabilizers, this includes cutting of the inner air sleeve and the welding of the stabilizers, should be charge to:

90025.4 35,500

② **Coal pipe restrictors should be charged to:

90025.5 43,300

① **Installation of outer air register lands and shrouds should be charged to:

90025.6 21,600

**Installation of platform along rear wall should be charged to:

90025.7 11,500 X

**Modification of the boiler feed pump pedestal should be charge to:

90025.8 3,600

xx Purch list items

.9 \$500

156,800

JAMES NELSON
92-50613
01.

EST.
FOR ALL 01
WORK \$125,000
MTL. \$6,000
SHROUDS